

**EMSL Analytical, Inc.**

29 North Plains Highway, Unit # 4, Wallingford, CT 06492  
 Phone/Fax: 203-284-5948 / (203) 284-5978  
<http://www.EMSL.com> [wallingfordlab@emsl.com](mailto:wallingfordlab@emsl.com)

EMSL Order: 241500013  
 CustomerID: ENVM50  
 CustomerPO: CK#110552  
 ProjectID:

Attn: **John Luby**  
**EnviroMed Services, Inc.**  
**470 Murdock Avenue**  
**Meriden, CT 06450**


Phone: (203) 238-4846  
 Fax: (203) 238-4243  
 Received: 01/02/15 1:25 PM  
 Analysis Date: 1/2/2015  
 Collected: 1/2/2015

Project: **PUTNAM HIGH SCHOOL**

**Test Report: Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM)**  
**Performed by EPA 40 CFR Part 763 Appendix A to Subpart E**

Sample	Location	Volume (Liters)	Area Analyzed (mm <sup>2</sup> )	Non Asb	Asbestos Type(s)	# Structures		Analytical Sensitivity (S/cc)	Asbestos Concentration	
						≥ 0.5μ < 5μ	≥ 5μ		(S/mm <sup>2</sup> )	(S/cc)
138 241500013-0001	INSIDE CLASSROOM #38	1278.00	0.0660	0	None Detected			0.0046	<15.00	<0.0046
139 241500013-0002	INSIDE CLASSROOM #34	1269.00	0.0660	0	None Detected			0.0046	<15.00	<0.0046
140 241500013-0003	INSIDE HALLWAY	1251.00	0.0660	0	None Detected			0.0047	<15.00	<0.0047
141 241500013-0004	INSIDE CLASSROOM #44	1242.00	0.0660	0	None Detected			0.0047	<15.00	<0.0047
142 241500013-0005	INSIDE CLASSROOM #47	1242.00	0.0660	0	None Detected			0.0047	<15.00	<0.0047

Analyst(s)  
 \_\_\_\_\_  
 William Shedrawy (5)

  
 \_\_\_\_\_  
 Gloria V. Oriol, Laboratory Manager  
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. Results reported in both structures/cm3 and structures/mm2 are dependent on the volume of air sampled and measured by non-laboratory personnel are not the responsibility of EMSL and are not covered by the laboratory's NVLAP accreditation. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.  
 Samples analyzed by EMSL Analytical, Inc. Wallingford, CT NVLAP Lab Code 200700-0, CT PH-0322, MA AA000191, RI AAL-108T3, VT AL357101

Initial report from 01/02/2015 16:42:53